INDEX OF 1978 ARTICLES

TITLES OF ARTICLES

Auto-Audio Update ..... Jan. 28
Auto Radio Tips ..... Mar. 14
Betamax Videotape, Part 1, videotape basics ..... Apr. 22
Betamax Videotape, Part 2A, recording B & W .... May 61
Betamax Videotape, Part 2B, Betamax B & W..... Jun. 32
Betamax Videotape, Part 3, chroma recording ..... Jul. 45
Betamax Videotape, Part 4, comb filters ..... Aug. 41
Betamax Videotape, Part 5, servo systems ..... Sep. 29
Betamax Videotape, Part 6, servo circuits ..... Oct. 54
Betamax Videotape, Part 7, mechanical ..... Nov. 36
Betamax Videotape, Part 8, servicing tips ..... Dec. 18
Curing Horiz Drift, Part 1, ringing coils ..... Jul. 14
Curing Horiz Drift, Part 2, RC oscillator ..... Aug. 28
Curing Horiz Drift, Part 3, methods & tips ..... Oct. 38
GE Color Portable, Part 1, power supplies ..... Sep. 14
GE Color Portable, Part 2, horiz and HV..... Oct. 23
GE Color Portable, Part 3, vertical ..... Nov. 18
GE Color Portable, Part 4, vertical & sync tips .... Dec. 38
GE Projection TV..... Jun. 14
Industrial Electronics, Part 7, gates & truth tables. Jan. 36
Industrial Electronics, Part 8, logic probe ..... Feb. 48
Industrial Electronics, Part 9, NOT gates..... Mar. 24
Industrial Electronics, Part 10, clocks..... Apr. 59
Industrial Electronics, Part 11, DeMorgan's Law ... May 52
Industrial Electronics, Part 12, Schmitt triggers ... Jun. 24
Industrial Electronics, Part 13, timers & flip flops. . Jul. 20
Industrial Electronics, Part 14, toggles to counter. Aug. 37
Industrial Electronics, Part 15, 7-count flip flop ... Sep. 21
Industrial Electronics, Part 16, ripple counters .... Oct. 31
Industrial Electronics, Part 17, counting circuits .. Nov. 32
LED Tests..... Feb. 54
Magnavox Color TV, Part 8, touch-tune repairs.... Jan. 18
National Service Conventions ..... Oct. 19
Quasar's Compu-Matic Tuning, digital tuners..... Dec. 24
Service Management, Part 1, improved income.... Jan. 14
Service Management, Part 2, low productivity .... Feb. 28
Service Management, Part 3, P&L statements..... Mar. 20
Service Management, Part 4, balance sheets..... Apr. 54
Service Management, Part 5, profitable rates..... May 32
Service Management, Part 6, calculating rates .... Jun. 18
Service Management, Part 7, pricing plans..... Jul. 26
Service Management, Part 8, ratio analysis..... Aug. 25

Service Management, Part 9, fair rates ..... Sep. 35
Service Management, Part 10, service vs sales .... Oct. 44
Service Management, Part 11, parts profit ..... Nov. 13
Service Management, Part 12, analyzing costs .... Dec. 34
Signal-Seeking Radios ..... Feb. 40
Sylvania Color TV, Part 1, tuners & power ..... Feb. 18
Sylvania Color TV, Part 2, horiz & HV ..... Mar. 32
Sylvania Color TV, part 3, vertical sweep ..... Apr. 34
Sylvania Color TV, Part 4, AGC circuits ..... May 42
Sylvania Color TV, Part 5, video ..... Jun. 41
Sylvania Color TV, Part 6, chroma circuits ..... Jul. 30
Slvania Color TV, Part 7, sound & audio ..... Aug. 19
Technical Notebook, Part 1, test questions ..... Feb. 34
Technical Notebook, Part 2, resistance tests ..... Mar. 41
Technical Notebook, Part 3, magnetic domains ... Apr. 49
Technical Notebook, Part 4, capacitor questions .. May 37
Technical Notebook, Part 5, magnetic strength ... Jun. 38
Technical Notebook, Part 6, diode protection ..... Jul. 38
Technical Notebook, Part 7, magnetic memories .. Aug. 47
Technical Notebook, Part 8, uncharged capacitors Sep. 39
Technical Notebook, Part 9, magnet core, in-situ Oct. 47
Technical Notebook, Part 10, dielectric effects ... Nov. 42
Technical Notebook, Part 11, dielectric changes .. Dec. 46
TV Brightness Problems ..... May 16

AUDIO
Auto-Audio Update ..... Jan. 28
Auto Radio Tips ..... Mar. 14
Signal-Seeking Radios ..... Feb. 40
Sylvania Color TV, Part 7, sound IF & audio ..... Aug. 19

BUSINESS
Analyzing True Costs ..... Dec. 34
Balance Sheets ..... Apr. 54
Calculating Labor Rates ..... June 18
Improving Income ..... Jan. 14
Increasing Parts Profits ..... Nov. 13
Low Productivity Cures ..... Feb. 28
Pricing Philosophy ..... Jul. 26
Profitable Service Rates ..... May 32
Profit and Loss Statements ..... Mar. 20
Proving Rates Are Fair ..... Sep. 35
Ratio Analysis ..... Aug. 25
Separate Profits of Sales & Service ..... Oct. 44

COLOR TV
GE Horizontal & HV ..... Oct. 23
GE Power Supplies ..... Sep. 14
GE Projection TV ..... June 14
GE Vertical Sweep ..... Nov. 18
GE Vertical & Sync Tips ..... Dec. 38
Horizontal Drift, Part 1 ..... Jul. 14
Horizontal Drift, Part 2 ..... Aug. 28
Horizontal Drift, Part 3 ..... Oct. 38
Magnavox Touch-Tune Servicing ..... Jan. 18
Quasar's Compu-Matic Tuning ..... Dec. 24
Sylvania AGC ..... May 42
Sylvania Sound IF & Audio ..... Aug. 19
Sylvania Tuners & Power Supplies ..... Feb. 18
Sylvania Horizontal & HV ..... Mar. 32
Sylvania Vertical Sweep ..... Apr. 34
Sylvania Video ..... Jun. 41
TV Brightness Problems ..... May 16

HORIZONTAL SWEEP & HV
GE Horizontal & HV ..... Oct. 23
Sylvania Horizontal & HV ..... Mar. 32

INDUSTRIAL ELECTRONICS
Clock Oscillators ..... Apr. 59
Clock and Flip Flops ..... Jul. 20
Counting Circuits ..... Nov. 32
DeMorgan's Law ..... May 52
Digital Gates and Truth Tables ..... Jan. 36
Flip Flops Count To 7 ..... Sep. 21
Logic Probes & Tests ..... Feb. 48
NOT Gates ..... Mar. 24
Ripple Counters ..... Oct. 31
Schmitt Triggers ..... Jun. 24
Toggles Can Count ..... Aug. 37

MISCELLANEOUS
Capacitor Questions ..... May 37
Dielectric Changes When Charged ..... Dec. 46
Diode Protection ..... Jul. 38
Effects Of Dielectrics ..... Nov. 42
LED Practical Tests ..... Feb. 54
Magnetic Cores & In-Situ ..... Oct. 47
Magnetic Domains ..... Apr. 49
Magnetic Memories ..... Aug. 47
Magnetic Strength ..... Jun. 38
National Service Conventions ..... Oct. 19
Resistance Tests ..... Mar. 41
Test Questions ..... Feb. 34
Uncharged Capacitors ..... Sep. 39

REPORTS FROM THE TEST LAB
Leader LBO-515 dual-trace delayed-trigger scope .. Feb. 58

VERTICAL SWEEP
GE AA Chassis Vertical Sweep ..... Nov. 18
GE Vertical Tips ..... Dec. 38
Sylvania Vertical Sweep ..... Apr. 34

VIDEO
Betamax Comb Filter Stops Crosstalk ..... Aug. 41
Betamax Chroma Recording ..... Jul. 45
Betamax Luminance Recording ..... May 61
Betamax Mechanical Systems ..... Nov. 36
Betamax Monochrome Playback ..... Jun. 32
Betamax Servicing Tips ..... Dec. 18
Betamax Servo Circuits ..... Oct. 54
Betamax Servo Operation ..... Sep. 29
Videotape Fundamentals ..... Apr. 22

SYMCURE

ADMIRAL
9M50, no high voltage ..... Jul. 6

GENERAL ELECTRIC
19JA, dark picture, screen controls don't work ..... Jul. 6

MAGNAVOX
T995, intermittent loss of tuner signal ..... Feb. 8
T995, CRT arcs damaged chroma IC ..... Feb. 8
T995, defective M114 PS module ..... Feb. 8
T995, retrace lines and poor linearity ..... Feb. 8
T995, excessive HV, HV adjust has no effect ..... Feb. 8
T995, no channel readout with STAR ..... Feb. 8
T952, dark picture, screen controls operate ..... Jul. 6

RCA
CTC38, picture is too bright ..... Jul. 6

CTC40, no high voltage, hot odor ..... Jul. 6
CTC71, blanking bar at right ..... Jan. 8
CTC71, horizontal won't lock, & regulated DC is high ..... Nov. 11
CTC71, repeated failure of horiz-output transistor . Dec. 11
CTC71AB, foldover near center of vertical ..... Apr. 21
CTC72, intermittent CRT heater ..... Jan. 8
CTC72, brightness causes video pulling at top .... Apr. 21
CTC72, intermittent picture & sound, then none,.. Nov. 11
CTC74, narrow picture ..... Jan. 8
CTC74, at high brightness, power relay chatters .. Apr. 21
CTC74, intermittent height or vertical locking ..... Apr. 21
CTC74, R510 & R508 overheat, & RF401 is open .. Nov. 11
CTC76, excessive brightness with retrace lines.... Apr. 21
CTC78, insufficient height with retrace lines..... Dec. 11
CTC81, poor focus, dim raster ..... Jan. 8
CTC81, channel motor runs constantly..... Jun. 8
CTC81, RF401 is open, and picture is dim ..... Nov. 11
CTC81H, channel motor runs continuously ..... Apr. 21
CTC85, no video or audio ..... Jan. 8
CTC85, insufficient width ..... Aug. 8
CTC85, retrace lines, raster shrinks, & shut-down stops sound and raster ..... Aug. 8
CTC86, locks with horiz-blanking bar about 2" from left ..... Dec. 11
CTC86, no sound or raster ..... Aug. 8
CTC86A, sound begins, then shut-down stops sound & HV ..... Aug. 8
CTC90, horizontal pulling moves through picture . Nov. 11
CTC90, no power to TV; remote has power ..... Nov. 11
CTC90, intermittent loss of horiz lock ..... Dec. 11
CTC90, hum bars move up through picture ..... Dec. 11
CTC90, stationary horizontal bend in picture ..... Dec. 11
CTC90D, channel frequencies drift ..... Aug. 8
CTC90B, no raster, HV okay..... Aug. 8

SYLVANIA

D14, no picture, like bad AGC ..... Oct. 61
D14, weave in picture, like bad filter ..... Oct. 61
E01, horizontal bending ..... Oct. 61
E03, low brightness, looks like bad CRT ..... Oct. 61
E04, snow only at right edge of picture ..... Oct. 61
E04, on UHF, a bar of interference at top ..... Oct. 61
E44, no raster, HV okay ..... Jun. 12
E44, non-linear at top, no sweep at bottom..... Jun. 12
E44, delayed failures of horiz output..... Jun. 12
E44, intermittent vertical roll..... Jun. 12
E44, low contrast, no snow off channel..... Jun. 12
E44, good sound, but no picture or snow ..... Jun. 12

ZENITH

12FB12X (B&W) hold control can't lock vertical .... Mar. 5
14DC15, narrow picture, too bright, no horiz locking Jul. 6
19GC45, hum bars, insufficient height ..... Mar. 5
19GC45, intermittent brightness ..... Mar. 5
19GC45, circuit breaker trips ..... Mar. 5
19GC45, squeal, no HV, breaker trips ..... May 8
19GC45, no setup line, dark picture with green streaks ..... May 8
19GC45, no picture or sound; dim raster ..... May 8
19GC45, picture flashes, loses locking ..... May 8
19HC48, no brightness, but HV is okay ..... Sep. 11
23DC14, flutter on high-band VHF stations..... Mar. 5
23DC14, picture 2" narrow at each side ..... May 8
23DC14, no height ..... May 8
23HC45, can't adjust gray scale Sep.11
23HC45, picture smears at high brightness..... Sep. 11
23HC50, ieft third of picture is darker..... Sep. 11
25EC58, color smeared and color locking is loose . Sep. 11
25EC58, poor color locking ..... Sep. 11
25GC50, no height, or intermittent ..... Mar. 5

TROUBLESHOOTING TIPS

ANY BRAND

Transformerless TV, no picture or sound..... Aug. 8

BALLY

Fireball, pinball resetting ..... Feb. 16

GE

UA, sound but no raster..... Apr. 8
19Qb, lightning damage ..... Jul. 7
UA (B&W), poor vertical line..... Aug. 8

MAGNAVOX

T960 (B&W) vertical won't lock ..... Mar. 13

MOTOROLA

CL337-BM, no sound, breaker trips, ... Jan. 13
STS-934, vertical flickering ..... May 11
23TS-918A, circuit breaker trips ..... Jan. 12
TS929, breaker trips, TV is dead ..... Sep. 12

PANASONIC

AN-49, part of raster blacked out ..... Aug. 8
CT-26, vertical flip or poor locking ..... Mar. 13
T125-A, T126-A, raster without video..... Apr. 11

RCA

CTC51/52, black area moves up..... Mar. 12
CTC71AB, circuit breaker trips ..... Oct. 16
KCS169B, B&W, blackout after warmup..... Mar. 11

REALISTIC

TRC-57 CB radio, no reception, has noise..... Feb. 16

SANYO

21VG5, vertical stretch and roll..... May 11

SEARS SILVERTONE

562.10390, double troubles ..... Jun. 13
562.10110 (B&W), blanking bar at center ..... Jun. 13

SONY

KV1710, weak color, color too red ..... Jan. 2
VO-1600 VTR, frozen tape ..... Sep. 12

SYLVANIA

D19, pincushion parts run hot ..... Mar. 11
E01-17, double troubles..... Aug. 8

SYLVANIA & PHILCO

E20, E21, E22, weak color..... Nov. 12

WINDSOR

am/fm model 2136, hum, distortion & intermittent volume..... Feb. 15

ZENITH

14B38/Z (B&W), unstable horizontal ..... Apr. 8
14CC16Z, rapid vertical roll ..... Feb. 15
14Z8C50, no top convergence ..... Jul. 7
20YIC48, no color ..... Jan. 12
25ED58, loss of locking..... Sep. 12